

Photos-5/22/13



**View along Bank toward Main Diversion from Weir 3
Weir 2 is Visible**



Weir 3-End of Existing Weir Rock in Foreground



Weir 3



View Downstream along Bank toward Weirs 4 & 5 From Weir 3



Weir 4



View of End of Weir 4- Note Weaker Bank Material-More Likely to Erode



View from Weir 4 Downstream to Weir 5 along Bank



Current around Edge of Weir 5



View of Weirs 1 & 2 Looking Toward Diversion Structure