Photos-5/22/13

View along Bank toward Main Diversion from Weir 3
Weir 2 is Visible

Weir 3-End of Existing Weir Rock in Foreground

Weir 3

View Downstream along Bank toward Weirs 4 & 5 From Weir 3

Weir 4

View of End of Weir 4- Note Weaker Bank Material-More Likely to Erode

View from Weir 4 Downstream to Weir 5 along Bank

Current around Edge of Weir 5

View of Weirs 1 & 2 Looking Toward Diversion Structure