
Montana Fish, Wildlife & Parks **Bannack State Park BOARDWALK REPLACEMENT PHASE 1-B** near Dillon, Montana FWP Project No. - 7216431 Bannack State Park ocation **Location Map Vicinity Map** No Scale No Scale ONTAI MONTANA FISH, WILDLIFE AND PARKS **DRAWING INDEX DESIGN AND CONSTRUCTION** OSEPH ALLA Sheet Description Sheet Description RENERGER PHYSICAL ADDRESS: MAILING ADDRESS: PO BOX 200701 1522 9th AVENUE **Enlargement Plan** 5 Cover 1 HELENA, MT 59620-0701 HELENA, MT 59601 2 Materials Notes 6 Details TEL 406.841.4000 **Overall Plan** 3 7 Details FAX 406.841.4004 **Enlargement Plan** SIONAL https://fwp.mt.gov/aboutfwp/design-and-construction R.Rognlie 03-04-2024 Bannack State Park Boardwalk Replacement MONTANA FISH, DRAWN BY APPROVED BY DAT APPROVED BY: DATE: J. Renenger 03-05-2024 WILDLIFE & PARKS PHASE 1-B **Cover Sheet** CHECKED BY DATE APPROVED BY: DATE: APPROVED BY: DATE:



Recap of Owner Provided Materials Phase I-B

Description	Units	Total Qty	Comments
4" Deck Screws	EA	15444	Approx. 17 boxes of 900 screws per box. Ceramic coated lag screws with star drive
4X4 Stringers*	LF	3776	4X4X10 pressure treated for ground contact.

* Cost of installation of all stringers shall be included in the boardwalk installation unit costs in the proposal. Additional Contractor-supplied stringers will be necessary to complete the in-kind boardwalk replacement and shall be furnished by the Contractor. An estimated quantity of additional, Contractorfurnished stringers is listed in the Project Proposal.

Boardwalk segments by width	Units*	Qty	Comments	
4 foot wide	LF	70	Around Historic Church, north side	
5 foot wide	LF	324	North side of the street	
6 foot wide	LF	586	Both north and south sides of the street	
6 foot wide	LF	186	Around the Mead Hotel	
7 foot wide	LF	424	Both north and south sides of the street	
8 foot wide	LF	56	North side of the street	
13'X19' landing at jog	SF	247	North Side of the street	
15'X20' landing at jog	SF	300	South Side of the street	
10'X16' landing at jog	6' landing at jog SF 160 South Side of the street		South Side of the street	

Recap of Existing Bannack Boardwalk Measurements NOT Including the newly replaced boardwalk in Ph.1-A

*Unit LF is lineal feet of Boardwalk, not boards

Materials Notes

NOTES:

Contractor shall use Owner supplied material that is stored on-site. Quantities of Owner 1. supplied material is listed on sheet 2. Contractor shall supply any additional material needed to replace boardwalk per the project proposal.


2. Any fill needed must be mechanically compacted to approx. 90%. Compaction method to be approved as a submittal. Imported fill must be 3/4" gravel base course meeting MPWSS Section 022235.

3. Screws must be driven flush with board surface.

4. Areas shown as "truck crossing" will be regularly driven across by trucks up to 1-Ton for maintenance access. Fill must be placed flush to the boardwalk edges per detail.


5. Contractor responsible for field verifying existing conditions.


6. Boardwalk boards must be whole boards, not spliced except at pads/landings and corners.




R.Rognlie	03-04-2024				
DRAWN BY:	DATE:	APPROVED BY:	DATE:	APPROVED BY:	DATE
J. Renenger	03-05-2024				
CHECKED BY:	DATE:	APPROVED BY:	DATE:	APPROVED BY:	DATE


MONTANA FISH, WILDLIFE & PARKS






R.Rognlie	03-04-2024		
DRAWN BY:	DATE:	APPROVED BY:	DATE:
J. Renenger	03-05-2024		
CHECKED BY:	DATE:	APPROVED BY:	DATE:







R. Rognlie 03-04-2024				
DRAWN BY: DATE:	APPROVED BY: DATE:	APPROVED BY: DATE:	MONTANA FISH,	Б
J. Renenger 03-05-2024			WILDLIFE & PARKS	Ρ
CHECKED BY: DATE:	APPROVED BY: DATE:	APPROVED BY: DATE:		•