



Photo 1. Little Blue Joint Creek, looking downstream at the inlet of the Road 5658 culvert at low flows



Photo 2. Little Blue Joint Creek, looking upstream at the outlet of the Road 5658 culvert at low flows



Photo 3. Looking downstream at the inlet. Upper half of culvert barrel has scoured to bare metal




Photo 4. From the inlet, a closer look at the scoured bare portion of the culvert barrel



Photo 5. Looking upstream through the culvert barrel towards the inlet




Photo 6. Looking downstream through the culvert barrel towards the outlet




Photo 7. Little Boulder Creek, looking downstream from the outlet of the Road 5658 culvert



Photo 8. Little Blue Joint Creek, looking upstream from the inlet of the Road 5658 culvert



Photo 9. The Road 5658 culvert crossing of Little Blue Joint Creek